

775 473

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	160	(steady adj state) adj resistance	US-PGPUB; USPAT; EPO; JPO; IBM_TDB	OR	OFF	2005/08/05 13:05
L2	12462	gas adj sensor	US-PGPUB; USPAT; EPO; JPO; IBM_TDB	OR	OFF	2005/08/05 13:06
L3	376	gas adj (sensing adj element)	US-PGPUB; USPAT; EPO; JPO; IBM_TDB	OR	OFF	2005/08/05 13:06
L4	12613	L2 or L3	US-PGPUB; USPAT; EPO; JPO; IBM_TDB	OR	OFF	2005/08/05 13:06
L5	2	1 and 3	US-PGPUB; USPAT; EPO; JPO; IBM_TDB	OR	OFF	2005/08/05 13:06
L6	20	("4259292"   "4397888").PN. OR ("4587104").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2005/08/05 13:38
L7	0	1 and 6	US-PGPUB; USPAT; USOCR	OR	OFF	2005/08/05 13:39
L8	0	calibrate and 6	US-PGPUB; USPAT; USOCR	OR	OFF	2005/08/05 13:40
L9	6441	3 or 2	US-PGPUB; USPAT; USOCR	OR	OFF	2005/08/05 13:40
L10	16	1 and 9	US-PGPUB; USPAT; USOCR	OR	OFF	2005/08/05 13:40
L11	0	calibrate and 10	US-PGPUB; USPAT; USOCR	OR	OFF	2005/08/05 13:58
L12	7	calibrate and 3	US-PGPUB; USPAT; USOCR	OR	OFF	2005/08/05 13:58
S1	12462	gas adj sensor	US-PGPUB; USPAT; EPO; JPO; IBM_TDB	OR	OFF	2005/08/04 14:37

S2	376	gas adj (sensing adj element)	US-PGPUB; USPAT; EPO; JPO; IBM_TDB	OR	OFF	2005/08/04 14:37
S3	0	gas adj (sensing adj means)	US-PGPUB; USPAT; EPO; JPO; IBM_TDB	OR	OFF	2005/08/04 14:37
S5	90490	steady adj state	US-PGPUB; USPAT; EPO; JPO; IBM_TDB	OR	OFF	2005/08/04 14:38
S6	0	pre-heating adj gas adj sensor	US-PGPUB; USPAT; EPO; JPO; IBM_TDB	OR	OFF	2005/08/04 14:39
S7	0	pre-heating adj (gas adj sensor)	US-PGPUB; USPAT; EPO; JPO; IBM_TDB	OR	OFF	2005/08/04 14:39
S8	0	pre adj heating adj (gas adj sensor)	US-PGPUB; USPAT; EPO; JPO; IBM_TDB	OR	OFF	2005/08/04 14:40
S9	90	heating adj (gas adj sensor)	US-PGPUB; USPAT; EPO; JPO; IBM_TDB	OR	OFF	2005/08/04 14:40
S10	0	heating adj (gas adj sensor) same S5	US-PGPUB; USPAT; EPO; JPO; IBM_TDB	OR	OFF	2005/08/04 14:41
S11	1	heating adj (gas adj sensor) and S5	US-PGPUB; USPAT; EPO; JPO; IBM_TDB	OR	OFF	2005/08/05 13:05